
## Online Submittal Instructions for device test data for the City of Wyoming Cross Connection Program

The web submittal of device test data is a simple process. You will enter the data on a web form and be prompted to submit the data once you are confident that the web form is complete. Once the data is submitted you will receive a confirmation email with an attached copy of the completed test form in pdf.


To begin, go to our website <a href="www.wyomingmi.gov">www.wyomingmi.gov</a>. Under departments choose utilities, then choose the cross connections page, followed by <a href="submit Test Results">Submit Test Results</a> (you can bookmark our web site to your Internet favorites). You will then enter your user name and password (provided by the City of Wyoming) to log into our system (Figure 1). You will then be required to enter the seven digit location code for the facility where the tests were completed (Figure 2) or you can enter the serial number of a device located at the facility. Location codes are entirely alphabetical (no numbers are used). The facility's test notification letter will have the location code and a list of backflow devices installed at the facility. If you are missing this code or the device serial number, please contact the facility owner or email us at crossconnections@wyomingmi.gov.


If you have a problem logging into the system, close your browser and start over from the "Submit test results" link on our Cross Connection web site. Do not attempt to change your password as your passwords are managed by us.





You then will be asked to choose the assembly for which to enter the test results for (Figure 3). If the facility has more than one assembly installed you can choose from a list of assemblies. Be sure to test all assemblies at the facility will be flagged as non-compliant until we receive the competed test results for all assemblies.





You also have the option for **replacing the existing assembly** if the assembly was changed out (Figure 4). If a device was replaced <u>do not enter a new device</u> but choose replace the selected assembly or there will be duplicate devices for the facility. Be sure to fill in the details (including the new serial number) for the replaced assembly when you enter the test results on the web form for the replaced assembly.


Assembly Information

Test Facility, 1234 MAIN STREET, WYOMING, MI, 49418

Backflow - On supply to treated boiler

Replace the selected assembly

Continue




You can also choose add new if a new assembly was installed at the facility (Figure 5). Again be sure to fill in a description (include the location) for the new assembly and complete the details when you enter the test results on the web form for the new assembly.

Figure 5b




Figure 5a




When you click continue the test form will open and allow you to enter your test results. Use the fields for each intial test.

NEW! For any device that fails the intial tests be sure to check the box (assembly failed) on the "Test Exceptions" section of the test form, (Figure 6a) use the comments field to note why the device failed. This will notify us that repairs are necessary and that the device will be retested in the future. (MDEQ requires us to track all failed devices).




**NEW!** As in the past, a contractor cannot delete an assembly. If an **assembly was removed check the box** (assembly removed) on the "Test Exceptions" section of the test form, (Figure 6b) use the comments field to note that the device was removed. This will notify us that we need to go out and verify why the device was removed.




Make sure to complete all the fields including the pass/fail, closed/open, service restored, and gauge readings. Choose the tester if your company has multiple testers, the test gauged used (Figure 7) gauge certification must be current, enter the tester certification number, and sign the form (some notation must be in the signature box).

## Figure 7a Company Name: City of Wyoming CC Program Date of Test: Please select.. Inspected By: Please select.. Tester Signature: Certification Numb 12122

Test gauge certification must be current





<u>Be sure to click save</u>. If any information is missing you will be prompted to finish completing the form before you can save the form. You will be given one more opportunity to review the data before you submit the assembly test results. Submitting the form is final and it cannot be modified once it is submitted.



Just a reminder, be sure to enter all the test results accurately as the CC Department will be reviewing your data. If you have any questions please call the CC Department at 616-261-3559 or email <a href="mailto:crossconnections@wyomingmi.gov">crossconnections@wyomingmi.gov</a>.

Once the completed device test form is saved and the data submitted, you will receive an email confirmation (to the email address you submitted) which will include a copy of the test results for for your records, see below.





					9	
		Account 1	information	_		
Facility Name: Test facility		Property Type: Manufacturing		Location Code: EOWKHQG		
Service Address: 1234 MAIN STREET, WYOMIN	iG, MI, 49418					
Mailing Name: Joe Blow			Phone: 616-234-4		567	
Mailing Address: 1234 MAIN STREET, WYOMIN	IG. MI 49418			Vec		
	000	77.00	Information			
Type: DCV	Assembly Description: Backflow (On supply to fire protection)					
Manufacturer: AMES	Model: ss2000		Serial Number: 12548		Size: 4"	
Check Valve #1						
Initial Test:	Held at (PSID): 10		Closed Tight		Leaked	
Repairs and Materials Used	irs and Materials Used					
Final Test CV #1						
Final Test:	Held at (PSID):		Closed Tight		Leaked	
	-//	Check	Valve #2			
Initial Test:	Held at (PSID): 10		☑ Closed Tight		Leaked	
Repairs and Materials Used	14 177111					
Final Test CV #2						
Final Test: Held at (PS		SID):	Closed Tight		Leaked	
Tester Information						
Test Gauge Maker/Model: Watts		Serial Number: 12345		Cal/Accuracy Date: 02/12/14		
Comments:		-				
The above is certified to be true	ftesting		Service Restored: ⊮ Yes ∷ No			
Company Name: Company		Company Address: 2350 Ivanrest Ave. S.V	pany Address: Ivanrest Ave. S.W., Wyoming, MI, 49418			
Inspected By: Tom Engelsma		Date of Test: 2/10/2014		Phone #: (616) 261-3568		
Tester Signature.			Certification Number: 01-25			

Return to: the Cross Connection Dept (crossconnections a wyomingmi.gov)